

COMMENTS AND RATINGS

West Lothian Trusted Trader Scheme

Allbright Electrical Contractors

NUMBER OF FEEDBACK FORMS RECEIVED: 104 (showing most recent 30)

AVERAGE SATISFACTION SCORE (OUT OF 10): 9.8

The following feedback forms have been completed by previous customers, rating their experience of dealing with Allbright Electrical Contractors.

ONLINE FEEDBACK PROVIDED	Date received: 1st September 2025				
	Total cost of w	ork: £492			
	Description of work: Installing 7 lights at my new home, adding a switch for an alarm, installing a dimmer switch in the en-suite bathroom.				
	Comments: David and Callum are a father and son business. They work well together, where there wer issues they explained the options clearly so a decision could be made, they provide an exceptionally high quality of workmanship, they both have a good sense of humour and I'd recommend them as they do a quality job.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 22 nd May 2025				
	Total cost of w	ork: Not provic	led.		
	Description of work: Completed 4 LED fire rated down lights in my bathroom				
	Comments: He was very professional and quick at getting back to me. He fitted my lights when he said he was going to and great price for the work he done defo recommend to others.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

Total cost of the work £ 1.500 Description of the work undertaken: 1.500 Description of the work undertaken:	Date received: 20 th May 2025 Total cost of work: £1500 Description of work: Installation of Ohme EV charger. Comments: Very happy with work. Communication clear and timely. Very professional and friendly service.			
Your comments: Very happy with work Cammina har clear				
and truly. Very preferrand and french	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

Total cost of the work £	Date received: 19 th May 2025			
Description of the work undertaken: NEW ELECTRICAL WIRING FOR NEW CITCHEN REMOVE OLD	Total cost of work: Not provided. Description of work: New electrical wiring for new			
BOARD HND FIT NEW FUSEBOARD WITH RCBOS	kitchen. Remove old board and fit new fuseboard with RCBOs.			
	Comments: Good workers.			
Your comments: _ (z 000 WORKERS	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 5 th December 2024			
	Total cost of w	ork: £2700		
	Description of work: Replace all lights to LED ceiling panels. Comments: Excellent workmanship, professional, polite and clear. Skilled and turned up on time on both days, efficient and transparent and honest.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 24th October 2024				
	Total cost of w	ork: £900			
	Description of work: Home EV charger installed.				
	Comments: Great service, efficient and very professional and friendly. Completed work with mess left behind.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 1st October 2024				
	Total cost of w	ork: Not provid	led		
	Description of work: Outside lighting, including fro door down lighters and security lights; and smoke/heat/ CO2 alarms fitted throughout inside Comments: Excellent service and extremely professional company. Cannot fault and have no hesitation in recommending.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 1st July 2024 Total cost of work: £262			
	Description of work: EICR for a completion certifical Comments: First time using Callum and would definitely recommend. We needed an EICR to provide to the council to obtain a completion certificate for works completed some time ago. Callum had availability within the week and job wa done within an hour. Full report to the council and certificate received. Thanks again.			ould R to on ago. d job was
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 26 th April 2024			
	Total cost of w	ork: £610.63		
	Description of work: Various small jobs. New light at back door. Replace bathroom mirror. Replace chrome shaver socket. Replace wall mounted circula mirror. Supply and fit lithium co detector. Various sockets replaced/repaired. TV aerial booster fitted. Comments: Excellent work by a father and son team They arrived early and just worked their way through the various jobs, including some 'add-ons' on the day. Tidied up impeccably at the end. Would highly recommend them.			
	Value for Quality of Service Tid work			Tidiness
Customer Ratings (Out of 10)	9	9	9	10

ONLINE FEEDBACK PROVIDED	Date received: 12 th April 2024 Total cost of work: £1068				
	Description of work: Outdoor socket box changes, installation of outdoor wall lights and floodlight. Unde kitchen cabinet LED lights and wall mirror light installation.				
	Comments: Very unprofessional. Father and son who bicker with each other all day and huff and puff their way through work. Messy and disorganised. Disrespectful towards private things in my home and lack of concern for leaving doors wide open while raining and cold outside and having a small dog in the house that could have escaped. Quick and happy to quote with nothing being a problem. Very different attitude once they start the work.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	7	7	1	1	

Trader right to reply:

As shown by other very positive reviews on this website, we have, for more than 34 years been a well respected and highly rated company.

As this is the second time we have worked for you we are saddened you could not approach us with your comments before you posted them on various places on the internet.

ONLINE FEEDBACK PROVIDED		received: 25 th January 2024 cost of work: £192				
	which best su unit, and set u regarding hall	Description of work: 1. Advise on new shower unit which best suited my needs. 2. Install new shower unit, and set up same. 3. Correct wiring faults regarding hall light switches. 4. Reconnect ceiling pendant unit and test same.				
	promised. The allocated to ca without a brea reasonable tin regarding the with that effici	Comments: 'Allbright' made the initial visit as promised. They were punctual on the day they allocated to carry out the job. They both worked without a break and completed the tasks in a very reasonable time frame. They encountered a snag regarding the plumbing of the old shower, but dealt with that efficiently. I was made aware of the costs well in advance, and was happy with the quoted charge.				
	Value for money	Quality of work	Service	Tidiness		
Customer Ratings (Out of 10)	10	9	10	10		

ONLINE FEEDBACK PROVIDED	Date received: 25 th April 2022				
	Total cost of work: £1105.48				
	Description of work: Installation of an electric car home charging point, including initial survey of the location. UK government grant deducted from invoice. Comments: Installed on final day eligible for grants, and Allbright made sure this happened. The work was done professionally, and all relevant paperwork was supplied ASAP to enable additional claim for Scottish grant. The associated app was demonstrated upon completion. I would definitely recommend Allbright.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	9	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received:	25 th April 2022	2	
	Total cost of w	ork: £96		
	Description of behind television		•	
	Comments: Alt managed to sle couple of days appointment til on completion Wouldn't hesita certainly use the	ot my job into t . David and Ca me, are always of the work, le	heir schedule allum arrived s polite and fr ft the area ne	e within a at the iendly and eat and tidy.
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received	Date received: 14 th March 2022			
	Total cost of w	ork: £72			
	Description of work: Identify faulty underfloor heating which was causing the system to trip.			oor heating	
	Comments: Very prompt service which is ideal when you don't know why most of the electrics in your house are not working. Much appreciated.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received:	-	2022	
	Description of work: Installation of EV charge point my home address including design and commissioning and support through the grant application process. Comments: The guys have been brilliant from star			
	Comments: The finish - really prinstallation the exceptional level took place before what was requexplained in further projects recommended	rofessional an y were on time yel and ensure ore they left my ired to be done Il detail. You c thesitate to us s I may have a	d on the day e, worked to a d that a full h y premises. A e and why we ould not ask t se them again nd would high	of the in andover all details of ere for more in for any
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: Total cost of w Description of electric car characteristic car characteris	ork: Not provided arger unit. nought they we contact they arrovided quote a cor the work to be lation day they and of people you wed me how to the and house was complete. Wou	ded. d and installed anged to come done at a were puncture ou can talk to o work every as all clean a all d not hesita.	essional, ne out n, then convenient al, polite, and ask thing nd tidy te to use
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received:	12 th May 2021		
	Total cost of w	ork: £450		
	Description of kitchen refurb.	work: A lot eled	ctrical wires t	o sort as
	Comments: Fir earth which alv intend to have company you o	vays good. I've them back aga	e used few tin ain. An electri	nes and
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received:	10 th May 2021		
	Total cost of w	ork: £375		
	Description of supply to new sockets and lig waterproof out Comments: Ex and were flexible looking at option house. Friendly recommended	summer house thing. Supplied door socket at a cellent service ole in dealing wons to supply py and tidy expensions.	e and first fit v d, wired and f rear of prope . Provided gr vith requireme ower to a nev	viring for fitted twin erty. eat advice ents when w summer
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

	T			
ONLINE FEEDBACK PROVIDED	Date received:	21st September	er 2020	
	Total cost of w	ork: £40		
	Description of	work: Outside	light fitted.	
	Comments: Gr friendly and ch would definitely	atty. Everythin	g was left ve	ry tidy;
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Grasen put BACK TO ORIGINAL STATE	Description of the work of CARLE GRANTS Description of the work undertaken: WALL DRIVED IN BEDROOM TO PUSH CARLE OUT SIDE 45 OF CARLE RUN ALONG GORDEN, DUG DOWN & RADINGEO BY INDERCRENO CHARGES GITTED AT BACK END OF GORDEN YOUR COMMENTS:	Date received: Total cost of w Description of cable outside, down and replayed back end of gather day arrived Garden put ba	ork: OLEV/ES work: Wall drill 45 of cable run aced by workmurden. uys were in tou on time. Job of	T GRANTS ed in bedroom along garde nen. Charger ch before sta	n, dug fitted at art day, on
money work	DAY ARRIVED ON TIME JOS DONE & PLACE TROY.	Value for	Quality of	Service	Tidiness

ONLINE FEEDBACK PROVIDED	Date received:	4 th September	2020	
	Total cost of w	ork: £587		
	Description of new 10 way ar	•		er unit with
	Comments: Fa Electrical Cont a quote for rep Received a qu was completed detailed quote. very profession	ractors Ltd. Co lacing our old ick response to I within a few o Would definite	ontacted them consumer un o our request lays of receiv	n to provide it. and job ing the
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

	Т			
ONLINE FEEDBACK PROVIDED	Date received:	26th August 20	020	
	Total cost of w	ork: £593.66		
	Description of box. Re-purposelectrical switch lighting.	se two electric	sockets, rew	rire
	Comments: The electricians were punctual and friendly. They kept me informed as to how the w was progressing. Everything was left clean and will definitely use the firm again.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Description of the work undertaken: Y2 EXTERNAL ELECTRICAL SOCKAS Your comments:	Total cost of v	l: 16 th July 2020 vork: Not provident work: x2 extent ery courteous, idy.	ded nal electrical	
Very Curteaus, easy to speak with-	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10
	1	•	•	

Total cost of the work £	Date received:	25 th February	2020	
Description of the work undertaken: Install Pico Sfor Unit for electric towel pail and install toward lail in Buthroom. Install lied Outside light. Replace existing Spotlights With Led Spotlights Your comments:	Total cost of w Description of towel rail and in I.e.d outside light. I.e.d spotlights Comments: 1st	work: Install Ronstall towel rail ht. Replace ex	CD spur unit I in bathroom	. Install
Ist class service.	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	9

Description of the work undertaken: Shalallaian of Hob Oken + Mealed Yowel Rail. Culside security lights. Reparted switch on Electric Fite. Your comments: Very professional and compelent persons. Eaplained everylling in a concise manner Have no hesitation in recommending to my friends of family.	Date received: Total cost of w Description of heated towel r switch on elec Comments: Ve persons. Expla Have no hesita and family.	vork: N/A work: Installat ail. Outside se tric fire. ery professiona	ion of hob, o curity light. F al and compe ng in a concis	Repaired etent se manner.
	Value for money	Quality of work	Service	Tidiness
ustomer Ratings (Out of 10)	10	10	10	10

Total cost of the work £	Date received: 13 th December 2019			
Description of the work undertaken: INSTRUMENTAL TOOMNUGHTS (REPLACEMENTS) PEPLACING OLD CONSUMER UNIT WITH	Total cost of w	work: Installing	7 downlights	
Your comments: WORK ARRIED OUT TO A HIGHSTADANA	(replacements). Replacing old consumer unit with new consumer units with RCBO's. Comments: Work carried out to a high standard. Punctual, courteous and respectful of my property			
PONCTUAL, COURTEOUS AND RESPECTEUR	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work €	Date received: 15 th October 2019			
Description of the work undertaken: REPLACE FUGE BOX IN OARAGE	Total cost of work: Not provided Description of work: Replace fuse box in garage.			
TO THE BOX IN OTRIOR				jarage.
Your comments: Good, friendly service and turned up when they said they would	Comments: Good, friendly service and turned up when they said they would.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	10	10	10

Total cost of the work £	Date received: 10 th October 2019				
Description of the work undertaken:	Total cost of work: Not provided				
PAT TESTING Spotlight Ends Replacement Light Inthing replacement Cleatrical Sunth repair	Description of work: PAT testing. Spotlight bulb replacement. Light fitting replacement. Electrical switch repair.				
Your comments: Excellent! Lots of additional much mos completed as meday - no need by a return wsit. Polite, mendly, helpful electricism - will def. recommend	Comments: Excellent! Lots of additional work was completed on Monday – no need for a return visit. Polite, friendly, helpful electricians – will def. recommend.				
	Value for money	Quality of work	Service	Tidiness	
ustomer Ratings (Out of 10)	10	10	10	10	

Total cost of the work £	Date received: 27 th September 2019			
Description of the work undertaken:	Total cost of work: Not provided Description of work: Power to external workshop. 8 x twin sockets, LED strip light, conduit, fuseboard, outdoor cable.			
Leid Strip light, Conduct, Essebagard, putdoor Cable				
Your comments: great Workmanship. Would use again 100%.	Comments: Great workmanship. Would use again 100%.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £	Date received: 27th August 2019 Total cost of work: Not provided Description of work: Old strip lights replaced in kitchen, oven and hob disconnected and new ones installed.				
Description of the work undertaken: OLD STRIP 4 GHB RAPLACED IN KITCHEN OVEN 6 HOB DISCONNECTED AND WEN ONES INSTALLED					
Your comments: OLD OVAN/1+0B WAS TRIPPING ELACTRICITY OFF CALLED ALCBRICHT AND THRY CARR KOLLYMAN DAY AND	Comments: Old oven/hob was tripping electricity off. Called Allbright and they came following day and located the issue. They returned to disconnect old cooker and install new one. Very accommodating.				
OLD COUMAN and INSTALL NAW ONA VARY ALLONDOMINA	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	