

NUMBER OF FEEDBACK FORMS RECEIVED: 436 (showing most recent 30)

AVERAGE SATISFACTION SCORE (OUT OF 10): 9.8

The following feedback forms have been completed by previous customers, rating their experience of dealing with Taylor Roofs.

ONLINE FEEDBACK PROVIDED	Date received: 6 th June 2025			
	Total cost of w	ork: £350		
	Description of work: They removed a disused flu from an old boiler and repaired the hole it left with new for and tiles. They also replaced chipped or broken tiles while up there. A clip holding a flu in place which we also broken was also replaced, this wasn't part of t job but was done anyway and I was very grateful. A work was photographed and shown to me on completion. Good honest reliable workmen Comments: Excellent customer service, quick, efficient and reliable roofers. We will be using them again and would highly recommend them to anyon looking for good workmanship. We had Dean & Sh very professional friendly pair.			vith new felt roken tiles e which was t part of the grateful. All e on n uick, sing them to anyone
	Value for Quality of Service Tidines			Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work $E = 362 = 66$	Date received: 30 th April 2025			
Description of the work undertaken:	Total cost of w	ork: £362.66		
EDGS DE RIDGE TILES PUT TTELED TO House AS BLED WERE ENTERING. DOWN-PLAS SECURD TO PROPERTY. Your comments: AU WORK SATISFACTORY TO WHAT I CAN	Description of work: Edge of ridge tiles put tighter to house as birds were entering. Downpipe secured to property.Comments: All work satisfactory to what I can see. 2 workmen were very professional and polite.			can see. 2
SEE. 2 workinger were VERY PAPPESSIDAAL & Politte.	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	8	9	10

ONLINE FEEDBACK PROVIDED	Date received: 22 nd April 2025			
	Total cost of w	ork: £675		
	Description of work: Roof tile storm damage			ge
	Comments: This is the second time I have used Taylor Roofs for roof repair work. I have experienced a friendly, efficient and trustworthy service in all aspects of their work.			xperienced
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	9	10	10

ONLINE FEEDBACK PROVIDED	Date received: 25 th March 2025			
	Total cost of w	ork: £7600		
	Description of work: Replacement of lead valleys, slate tile repairs.			valleys,
	Comments: Excellent, all work carried out on time and to an excellent standard. Highly recommended.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received:	24 th March 20	25	
	Total cost of w	ork: £140		
	Description of work: Gutters and valleys cleaned ar cleared of moss build up. Comments: Always my go-to roofers. Reasonable prices, professional job every time, invoice and paying process is super easy direct from link in emails.			leaned and
				e and
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 17 th March 2025			
	Total cost of w	ork: £3100		
	Description of work: Replacement of flashing, and roof tiles blown off due to the high winds in January Comments: I had used this company before and could not fault them, we were kept well informed as and when the work would be carried out.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 17th March 2025			
	Total cost of w	ork: £595.58		
	Description of work: Repair damaged to roof cauby by Storm Eowyn and clean guttering.			oof caused
	Comments: I would thoroughly recommend Taylor Roofs. Everyone you speak to is kind, efficient, caring and knowledgeable. The work is carried out efficiently, speedily and any old slates/rubbish etc are removed.			
	Value for Quality of Service Tidir money work			Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: Total cost of w		25	
	Description of Comments: A from start to fir and helpful.	pleasure to dea	al with this co	ompany
			Tidiness	
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 11 th March 2025			
	Total cost of w	ork: £192		
	Description of work: Repair storm damage to chimney stack			e to
	Comments: Very pleased with work. This is 2nd job Taylor Roofs has done for me. Other job was a roof repair which I was very pleased with.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 5 th March 2025			
	Total cost of w	ork: £218		
	Description of work: The job was to find and fix a le in my garage roof.			nd fix a leak
	Comments: I was very happy all round with the work and would recommend.			h the work
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 4 th March 2025			
	Total cost of work: £3800			
	Description of work: To replacing ridge tiles a checking rest of roof for any damage.			s and
	Comments: Job done and the boys were very tidy and cleaned up each night when finished. This is th 4th time that I have used Taylor Roofs as I get the roof surveyed every so often and they are always very helpful and only say if anything needs replacin they are an excellent company to deal with and would recommend to anyone.			
	Value for Quality of Service Tidi money Work			Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 26 th February 2025 Total cost of work: £582.82 Description of work: Replace ridge tiles. Comments: During the work, roofer noticed some			
	Total cost of work: £582.82 Description of work: Replace ridge tiles. Comments: During the work, roofer noticed some broken tiles so replaced them. Value for money Quality of work Service Tidiness			
	Description of work: Replace ridge tiles.			
	0			d some
			Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	9

-

ONLINE FEEDBACK PROVIDED	Date received: 26 th February 2025			
	Total cost of w	ork: £520		
	Description of work: Repairs to roof after recent storm.			
	Comments: Friendly, professional customer service and excellent workmanship.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 26 th February 2025 Total cost of work: £1235.44				
	 Description of work: E1235.44 Description of work: Remove gable end tiles on extension & lay to the side for later use. Remove all existing dry verge units & dispose Install new 25mmx50mm treated timber to barge board Resecure tiles Install dry verge units Replace missing end cap on new dry verge system on main roof with UPVC end cap to cover end ridge tile Fit new lead flashing at top of verge on extension using code 4 390mm lead Repair broken tiles Re fix tiles at verge on main roof that have come loose Comments: The staff were very friendly and efficient from initial quote stage to completing the work. The work was carried out quickly and they were especially helpful when we need a quicker works start date to help with elderly fathers home safety needs. I have used Taylor Roofs twice, each time I have been very happy with the standard of work and 				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 20th February 2025 Total cost of work: £932.77				
	Total cost of work: £932.77 Description of work: Storm Damage Repair - install new dry verge system Removal & disposal of existiverge units Install new treated timber to barge boar Re-secure tiles clipping / nailing every tile Install dr verge units interlocking them into each other & fixir at the head Complete dry verge system with UPVC end cap to cover end ridge tile Tidy site Comments: Previously used Taylor Roofs for a different repair job so returning customer. Taylor Roofs are always professional and courteous, provide quotes and explanations of work required,				
	and arrive / respond when expected. They completed the job to a highly professional standard and I would recommend them for any roofing work. They are my go to for roof jobs and I wouldn't consider approaching anyone else.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 20 th February 2025			
	I otal cost of w	Ork: £156		
	Description of work: Inspect roof for storm damag refix single roof tile and clean gutters.			damage,
	Comments: The team were very professional and th work was completed at a reasonable cost. It took a bit longer than I would have liked but that may have been due to the demand for roofing work following the major storm.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	10	10	9

ONLINE FEEDBACK PROVIDED	Date received: 20 th February 2025			
	Total cost of work: £135			
	Description of work: Sealed down building lead work that had come up with the recent high winds.			
	Comments: Completely professional and friendly from the initial enquiry through to survey, work being carried out and final payment.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 20th February 2025			
	Total cost of w	ork: £196.40		
	Description of work: Replace 2x Broken ridge tiles after storm blew them off and replaced broken tiles damaged by ridge tiles. Comments: Great Communication from trader and a done within a very busy period after the storm. Great service from a trusted trader.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 18 th February 2025 Total cost of work: £11427 Description of work: Stripping, reboarding and retilin of a sloped roof. Comments: A very professional business, shown through their slick website, prompt e-mail replies and the roofing crew boss who was unfailingly polite and friendly and always kept me informed about what was happening on site. They weatherproof as they go. The work was completed in 3.5 days and the ski removed the day after. You pay 35% up front before any work starts and pay the balance within 3 workin days after completion.			
	Value for Quality of Service Tic money work			Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 17 th February 2025			
	Total cost of work: £281			
	Description of work: Ridge tiles replaced.			
	Comments: Job well done, clean, tidy workers.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 12 th February 2025			
	Total cost of w	ork: £1300		
	Description of work: Roof tiles changed into ventilation tiles. Insulation put down.			to
	Comments: I am really happy at the work I got done. I was kept informed of what they were doing and they left my house that tidy you wouldn't know they had been! Lovely and friendly guys.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 14 th January 2025 Total cost of work: £650			
	Description of work: Repair chimney which was weakened by the elements. Clean surrounding are leaving roof tiles free from debris. Stopped leak inte chimney cavity. Comments: Excellent service as usual from Taylor Roofs. Professional survey followed up by quick ar			nding area d leak into m Taylor
	courteous tradesman repair. Highly recommended to a repeat customer.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ 3807. 67	Date received: 14 th January 2025				
Description of the work undertaken: INSTALL ING NEW DEEP FLOW GUTTERING IT INSTALLING DRY VERGE INTERLOCKING UNITS. Your comments: CONSIDERING IT WAS THE COLDEST DAY WE'VE HAD SOFAR	 Total cost of work: £3807.67 Description of work: Installing new deep flow guttering. Installing dry verge interlocking units. Comments: Considering it was the coldest day we've had so far this year, we got a professional job from Guy and Lewis. 				
THIS YEAR, WE GOT A PROFESSION JOB FROM GUY & LEWIS	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	8	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 13 th January 2025			
	Total cost of w	ork: £134		
	Description of work: Replaced dislodged tile			
	Comments: Couldn't fault Taylor Roofs kept in touch from start to finish came when they said they would and above all very friendly.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 7 th January 2025			
	Total cost of work: £2002			
	Description of work: removing old drainpipes and gutters and pvc above garage door and side of garage. Putting up new gutters around full house ar garage.			de of
	Comments: Done a great job really pleasant workmen when finished removed all old gutters and drainpipes. left really tidy. Would really recommend this company to anyone.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 6 th January 2025			
	Total cost of work: £132			
	Description of work: Replacing 2 cracked tiles on roof. Comments: This was a very small job and Taylor fitted me in within a couple of days. Excellent service.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 17 th December 2024				
	Total cost of w	Fotal cost of work: £250			
	Description of work: Roof repair to moved tiles and replacing an obsolete vent tile.			tiles and	
	Comments: Very easy to deal with from first call to survey/quote then repair. Roofing team were polite, very knowledgeable, quick and you would not even know they had been there afterwards. I would highly recommend this company.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 10 th December 2024			
	Total cost of work: £1200			
	Description of work: Two new gutters replaced and downpipe repaired. Comments: Very happy with outcome, workman thoroughly professional as are all office staff, would highly recommend Taylor Roofs.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 9 th December 2024 Total cost of work: £11,000			
	Description of work: Full roof, fascias and gutter replacement.			guttering
	Comments: Great customer service from start to finish. Kept in contact to check all ok. One small issue however was resolved very quickly. Friendly team. Work completed timely and area left as tidy a possible whilst scaffolding was still in place. Completely satisfied from initial contact to completion. Definitely recommend Taylor Roofs.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 28 th November 2024			
	Total cost of w	otal cost of work: £2300.04		
	Description of work: To bird and rodent proof the solar panels. Also, to replace the lead watergate the right hand side of the rear dormer.			
	Comments: All works carried out in a professional manner with friendly tradesmen who kept me informed as works progressed. The only downside was the long wait from me accepting the quote and paying a deposit to works beginning. We await some wet weather to assess whether or not the replacement lead watergate has cured the problem which we were experiencing!			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10