

COMMENTS AND RATINGS

West Lothian Trusted Trader Scheme

Taylor Roofs

NUMBER OF FEEDBACK FORMS RECEIVED: 460 (showing most recent 30)

AVERAGE SATISFACTION SCORE (OUT OF 10): 9.8

The following feedback forms have been completed by previous customers, rating their experience of dealing with Taylor Roofs.

	Т				
ONLINE FEEDBACK PROVIDED	Date received:	ceived: 17 th November 2025			
	Total cost of work: £8400				
	Description of work: Dry hip and ridge replacement				
	Comments: Very satisfied with all aspects of the Initial surveyor was very professional and knowledgeable and we were kept informed by the friendly office staff as to when the work would commence. Reece was with us for all four days made sure that we were kept up to date on progue the and all the other roofers were courteous throughout. All areas were left very clean and the completion. We would definitely recommend this company.			d by the buld days and n progress. Is and tidy on	
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	9	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 13 th November 2025				
	Total cost of w	ork: £5000			
	Description of work: New garage flat roof. Comments: We are really highly satisfied with the work completed on my mother's garage roof. The guys were great and highly skilled. They kept my Mum up to date with all the work and showed her photos of the progress. The office staff kept us informed and communicated very well with us. We highly recommend Taylor Roofs for a highly quality job. They even tidied up after themselves! I was ser out to sweep up but it had already been done. That doesn't happen very often!!				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

Total cost of the work £	Date received: 12 th November 2025			
Description of the work undertaken:	Total cost of work: £1991.50			
REPLACE WITH BRY RIDGE SYSTEM INCLUDING NEW TILE VENT FOR SHOWER EXTRATOR FAN BOHAUST.	Description of work: Remove bedded wet ridge tile system and replace with dry ridge system including new tile vent for shower extractor fan exhaust.			
Your comments: WORK BUDGETTED FOR ONE MAY BUT EXTENDED TO BAY DURATION DUE TO HIGH WIND.	Comments: Work budgeted for one day but extended to 6 day duration due to high winds.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	7	9	9	9

Total cost of the work £ \$3,915.54	Date received: 11 th November 2025			
Description of the work undertaken: Repair of a large roof join between two attacked	Total cost of work: £3915.54			
cottages	Description of work: Repair of a large roof join between two attached cottages.			join
	Comments: Job completed without any fuss.			
Too completed without any fiss.	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	N/A	10	10

Total cost of the work £ 765	Date received	Date received: 3 rd November 2025				
Description of the work undertaken: Removal of Sinds vents from under solar panels. Fit barried around solar panels to avoid future problem.	Description of under solar p	Total cost of work: £765 Description of work: Removal of birds' nests from under solar panels. Fit barrier around solar panels to avoid future problems.				
Your comments: A fees problems with corner materials but eventually sorted out.		Comments: A few problems with correct materials eventually sorted out.				
scred out.	Value for money	Quality of work	Service	Tidiness		
Customer Ratings (Out of 10)	10	N/A	10	10		
				•		
Total cost of the work £ £7511.55 MC VAT	Date received	Date received: 3 rd November 2025				
Description of the work undertaken:	Total cost of	Total cost of work: £7511.55 inc VAT				

Total cost of the work £ 4511:55 UNIC VAT	Date received: 3 rd November 2025				
Description of the work undertaken: New Flat roof, gutter and downpyes to garage	Total cost of work: £7511.55 inc VAT				
Patch aguin to state + lead	Description of work: New flat roof, gutter and downpipes to garage. Patch repairs to slate and lead.				
Your comments: I had a quote from another booker of £20k for works. Surreyor who came out to price you was knowledgeable A debuted broken down with was provided into Insurance cert. The works who undertak the work were great. Kept me updated, quality work and hidy.	undertack the work were great Kent me undeted				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

Total cost of the work £	Date received: 3 rd November 2025				
Description of the work undertaken: Replacing boken titles and repaining gotting + cleaning all	Total cost of work: Not provided				
the guitting.	Description of work: Replacing broken tiles and repairing gutting and cleaning all the guttering				
Your comments: The men were posite, and quick and stated, would recommend then + will use them again, hopefully for not a long time.	Comments: The men were polite, and quick and tidied, would recommend them and will use them again, hopefully for not a long time.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	9	9	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 22 nd October 2025				
	Total cost of w	ork: £1200			
	Description of work: Couple of slate replaced front and back of house and new down pipe and guttering on front of house				
	Comments: Excellent. They were very busy so you go in a list and they keep you updated with were yo are on list. They came to me very quickly, highly recommended as they were very easy to deal with.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 22 nd October 2025 Total cost of work: £1600			
	Description of work: We needed our gutters replace and some broken tiles, but also needed scaffolding so that did add to the cost. Comments: Taylor Roofs did a good job from starts.			
	Comments: Taylor Roofs did a good job from start to finish. We have used them before and would use again. We did have a few small issues but they were sorted promptly without any problems.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 17 th October 2025				
	Total cost of w	ork: £2352			
	Description of work: Roof cleaning of moss and a preventative solution applied. Comments: Roof cleaning of moss was completed over two days with a preventative solution applied a the end. Eight tiles were replaced after inspection when working to be cracked. From initial survey, to the work being completed was carried out in a satisfactory way. It was quite misty the weather and bit slippy on the roof, but an extra team was called it to help with the work. Excellent service work area lecter and tidy, old moss removed from site. Advice on roof vents to be installed later.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 15 th October 2025 Total cost of work: £2800			
	Description of work: Roof repair and slates were fixed.			
	Comments:			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 15 th October 2025				
	Total cost of w	ork: £3000			
	Description of work: Replace lead and tiles around chimney. Replace boards, felt and tiles to rear roof.				
	Comments: Very professional, arrived when promised, completed on time. High quality work. Hard working and tidy. Office staff are very responsive. Will definitely use again.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	8	10	10	10	

Total cost of the work £	Date received: 7 th October 2025				
Description of the work undertaken: Full filed roof replacement	Total cost of work: Not provided Description of work: Full tied roof replacement Comments: Excellent workers – a very professional job. Some nails have come through loft but that couldn't really be avoided – it has left some areas with broken plaster and paint.				
Your comments: Excellent worker - a very professional job some naile have come though loft but that					
couldn't really be avoided - it has left some	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	9	

ONLINE FEEDBACK PROVIDED	Date received: 7 th October 2025				
	Total cost of w	ork: £4630.26			
	Description of work: Renew flat roof, fascia and guttering. Comes with a 10year certificate of guarantee for materials and workmanship.				
	Comments: Blair and Craig came on time each morning, kept me informed, and worked hard to get the job completed before a storm was due. Very pleasant guys, tidied after themselves, and made the work go smoothly. I didn't get additional quotes due to paying £30 for their quote so not actually sure if this was a comparable price to what other companies would charge. However, I do have peace of mind now that the work is complete.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	8	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 3 rd October 2025			
	Total cost of work: £328			
	Description of work: Replacement roof tiles Comments: We contacted Taylor Roofing as we wished to have the roof surveyed before the winter months and it was found we required some broken tiles replaced. Greg & Daryl provided a very professional, efficient and friendly service informing us of all works being carried out and also clear up thereafter. From Mark, surveyor, Greg and Daryl and contact with all their customer care team, we would highly recommend Taylor Roofing for any further works. Thank you for an excellent job.			
	Value for Quality of Serv money		Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 25 th August 2025			
	Total cost of work: £3500			
	Description of work: Install dry ridge system and other roof repairs.			
	Comments: Great to deal with, quick to respond and work done to a high standard.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	9

ONLINE FEEDBACK PROVIDED	Date received: 1st August 2025				
	Total cost of w	ork: £4500			
	Description of work: Roof repair, specialists lead flashing.				
	Comments: First class job. Quality of workmanship was exceptional. Clean and tidy.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 28 th July 2025				
	Total cost of w	ork: £12,434			
	Description of work: Supply materials and fit a new roof.				
	Comments: They turned up when they said they would and did an excellent job. The workmen were polite and pleasant, it was obvious when watching them work they knew exactly what they were doing. The gardens were left tidy. All in, very satisfied with the work. They are not the absolute cheapest, but you get what you pay for. the materials were all top quality, and no corners were cut when carrying out the work. I would thoroughly recommend this company.				
	Value for Quality of Service Tidin work				
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 28 th July 2025			
	Total cost of w	ork: £1014		
	Description of work: Fix leaking roof by replacing broken tiles, also install 12 ventilation tiles to allow additional ventilation into the loft space. Comments: I was impressed by Taylor's service and wouldn't hesitate to use them again.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 14 th July 2025				
	Total cost of w	ork: Not provide	ed.		
	Description of work: Dry verge and Ridge replacement.				
	Comments: The guys were great. I could not ask for any better people to get the job done. Dry verge and Ridge replacement. I couldn't be any happier with the job.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 12 th July 2025			
	Total cost of work: £850			
	Description of work: Replaced loose roof ridge tiles.			
	Comments: From the initial phone call to completion of work we found no fault. A good company to deal with and all work satisfactory.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 26 th June 2025				
	Total cost of w	ork: Not provid	ed.		
	Description of work: We got our gutters replaced a downpipes replaced front and back.				
	Comments: Mark and Darryl were very nice and polite, got the job done, kept the place nice and tidy and were done in two days, cannot fault them, would highly recommend Taylor roofs if we need to get our roof replaced.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 25 th June 2025				
	Total cost of w	ork: £1712.86			
	Description of work: Put fascia all round garage an top edge.				
	Comments: Very pleased with the standards of wordone. Workmen were very good and answering any questions I had and left property very tidy. Office standards of wordone. Workmen were very good and answering any questions I had and left property very tidy. Office standards of wordone.				
	Value for money	Quality of work	Service	Tidiness	
Customer Ratings (Out of 10)	9	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 20 th June 2025 Total cost of work: £415				
	Description of work: Replaced 14 tiles with broker water gates.				
	Comments: Excellent. They fixed my leaking roof (something two other companies had come round and failed to do). Everything felt very professional with them - an actual booking system helped (agai other roofers would say they would come round bunever did), plus the surveyor took photos of the problem, explained it to me and sent through a detailed quote. Would definitely recommend.				
	Value for Quality of Service work			Tidiness	
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	Date received: 13 th June 2025			
	Total cost of work: £2800			
	Description of work: Roof repairs - dry ridge installation, valley replacement to both valleys at th front of my property, installation of new bird combs, replaced all broken and missing tiles, tidied up site. Comments: Very pleased with the job done. Job too 2 days to complete. Everything was tidied before the left.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 6 th June 2025			
	Total cost of work: £350			
	Description of work: They removed a disused flu from an old boiler and repaired the hole it left with new fee and tiles. They also replaced chipped or broken tiles while up there. A clip holding a flu in place which was also broken was also replaced, this wasn't part of the job but was done anyway and I was very grateful. A work was photographed and shown to me on completion. Good honest reliable workmen. Comments: Excellent customer service, quick, efficient and reliable roofers. We will be using them again and would highly recommend them to anyone looking for good workmanship. We had Dean & Shavery professional friendly pair.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Date received: 30th April 2025 Total cost of the work £ 36.2 . 66 Total cost of work: £362.66 Description of the work undertaken: Description of work: Edge of ridge tiles put tighter to RIDGE TILES PUT TIGHTER EDGE house as birds were entering. Downpipe secured to House AS BLADS WERE ENTERING. DOWNPLACE property. SECULOR 10 PROPERTY. Comments: All work satisfactory to what I can see. 2 workmen were very professional and polite. ALL WORK SAMSPACTORY TO WHAT I CAN SEE. 2 WORLINER WERE VERY PARESSIDARE Value for Quality of Service **Tidiness** a POLITE. work money Customer Ratings (Out of 10) 8 8 9 10

ONLINE FEEDBACK PROVIDED	Date received: 22 nd April 2025			
	Total cost of work: £675			
	Description of work: Roof tile storm damage. Comments: This is the second time I have used Taylor Roofs for roof repair work. I have experienced a friendly, efficient and trustworthy service in all aspects of their work.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	9	10	10

ONLINE FEEDBACK PROVIDED	Date received: 25 th March 2025			
	Total cost of work: £7600			
	Description of work: Replacement of lead valleys, slate tile repairs. Comments: Excellent, all work carried out on time and to an excellent standard. Highly recommended.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 24 th March 2025			
	Total cost of work: £140			
	Description of work: Gutters and valleys cleaned at cleared of moss build up. Comments: Always my go-to roofers. Reasonable prices, professional job every time, invoice and paying process is super easy direct from link in emails.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10