



COMMENTS AND RATINGS

West Lothian Trusted Trader Scheme

Taylor Roofs

NUMBER OF FEEDBACK FORMS RECEIVED: 468 (showing most recent 30)

AVERAGE SATISFACTION SCORE (OUT OF 10): 9.8

The following feedback forms have been completed by previous customers, rating their experience of dealing with Taylor Roofs.

ONLINE FEEDBACK PROVIDED	<p>Date received: 21st January 2026</p> <p>Total cost of work: £750</p> <p>Description of work: Fix leaking roof caused by tiles shifting after recent bad weather.</p> <p>Comments: The process from my initial call, through survey and quote, to fixing our roof leak was smooth and as fast as they could fit the work in. The Taylor Roofs team gave open communication and kept me well informed.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 21st January 2026</p> <p>Total cost of work: £4500</p> <p>Description of work: Strip and re felt garage flat roof.</p> <p>Comments: Trader kept me up to date until work started and although the weather was not very helpful all work was completed to my satisfaction and the site all cleared and left clean and tidy.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 19th January 2026</p> <p>Total cost of work: £142</p> <p>Description of work: Repair to boiler flue on roof</p> <p>Comments: Can thoroughly recommend Taylor roofs. Everyone I dealt with was polite courteous and professional and did everything that they said they would. Why can't all companies be like this?</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 15th January 2026</p> <p>Total cost of work: £159</p> <p>Description of work: Soil vent pipe leaking due to it not being routed & secured correctly. This was identified by Graeme, the surveyor, who took images of the problem and checked the vent & surrounding area on the roof. The pipe was routed and secured.</p> <p>Comments: From initial contact to completion of the work all staff I dealt with were friendly, professional and helpful. The surveyor and workmen came at the advised time and left the house as they found it. The cost of the repair was within the price range I expected. I would not hesitate to recommend / use Taylor Roofs in the future.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 8th January 2026</p> <p>Total cost of work: £404</p> <p>Description of work: Replaced roof tiles and roof lead to fix roof leaks.</p> <p>Comments: Excellent company, brilliant customer service and fantastic quality of work.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 12th December 2025</p> <p>Total cost of work: £540</p> <p>Description of work: Gutter and waterway clean on a large roof.</p> <p>Comments: Taylor Roofs are excellent - always send quotes, invoices and receipts. Give plenty of advice and flexibility for when work is completed. The workmen are always prompt and courteous, do the work thoroughly and leave the place clean and tidy. I would recommend them.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	7	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 9th December 2025</p> <p>Total cost of work: £760</p> <p>Description of work: Roof repair</p> <p>Comments: Excellent job, with no hassle whatsoever. Thank you very much, Taylor Roofs.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 26th November 2025</p> <p>Total cost of work: £493</p> <p>Description of work: Replacing roof tiles and mending the roof line.</p> <p>Comments: Excellent service from start to finish, what and Robbie who did the on-site work very professional and pleasant.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 17th November 2025</p> <p>Total cost of work: £8400</p> <p>Description of work: Dry hip and ridge replacement.</p> <p>Comments: Very satisfied with all aspects of the job. Initial surveyor was very professional and knowledgeable and we were kept informed by the friendly office staff as to when the work would commence. Reece was with us for all four days and made sure that we were kept up to date on progress. He and all the other roofers were courteous throughout. All areas were left very clean and tidy on completion. We would definitely recommend this company.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 13th November 2025</p> <p>Total cost of work: £5000</p> <p>Description of work: New garage flat roof.</p> <p>Comments: We are really highly satisfied with the work completed on my mother's garage roof. The guys were great and highly skilled. They kept my Mum up to date with all the work and showed her photos of the progress. The office staff kept us informed and communicated very well with us. We highly recommend Taylor Roofs for a highly quality job. They even tidied up after themselves! I was sent out to sweep up but it had already been done. That doesn't happen very often!!</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

<p>Total cost of work £ 1991.50</p> <p>Description of work undertaken: <u>REMOVE BEDDED WET RIDGE TILE SYSTEM AND</u> <u>REPLACE WITH DRY RIDGE SYSTEM INCLUDING NEW</u> <u>TILE VENT FOR SHOWER EXTRACTOR FAN EXHAUST.</u></p> <p>Your comments: <u>WORK BUDGETED FOR ONE DAY BUT EXTENDED TO</u> <u>6 DAY DURATION DUE TO HIGH WIND.</u></p>	<p>Date received: 12th November 2025</p> <p>Total cost of work: £1991.50</p> <p>Description of work: Remove bedded wet ridge tile system and replace with dry ridge system including new tile vent for shower extractor fan exhaust.</p> <p>Comments: Work budgeted for one day but extended to 6 day duration due to high winds.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	7	9	9	9

Total cost of the work £ Description of the work undertaken: Your comments:	£3,915.54 Repair of a large roof join between two attached cottages Job completed without any fuss.	Date received: 11 th November 2025 Total cost of work: £3915.54 Description of work: Repair of a large roof join between two attached cottages. Comments: Job completed without any fuss.		
Customer Ratings (Out of 10)	9	N/A	10	10

Total cost of the work £ Description of the work undertaken: Your comments:	£765 Removal of birds nests from under solar panels. Fit barrier around solar panels to avoid future problems A few problems with correct materials but eventually sorted out.	Date received: 3 rd November 2025 Total cost of work: £765 Description of work: Removal of birds' nests from under solar panels. Fit barrier around solar panels to avoid future problems. Comments: A few problems with correct materials but eventually sorted out.		
Customer Ratings (Out of 10)	10	N/A	10	10

Total cost of the work £ Description of the work undertaken: Your comments:	£7511.55 inc VAT New flat roof, gutter and downpipes to garage Patch repairs to slate + lead I had a quote from another roofer of £20K for works. Surveyor who came out to price job was knowledgeable. A detailed broken down cost was provided with insurance cert. The roofers who undertook the work were great. Kept me updated, quality work and tidy.	Date received: 3 rd November 2025 Total cost of work: £7511.55 inc VAT Description of work: New flat roof, gutter and downpipes to garage. Patch repairs to slate and lead. Comments: I had a quote from another roofer of £20K for works. Surveyor who came out to price job was knowledgeable. A detailed broken down cost was provided with insurance cert. The roofers who undertook the work were great. Kept me updated, quality work and tidy.		
Customer Ratings (Out of 10)	10	10	10	10

<p>Total cost of the work £</p> <p>Description of the work undertaken:</p> <p><i>Replacing broken tiles and repairing gutting + cleaning all the guttering.</i></p> <p>Your comments:</p> <p><i>The men were polite, and quick and tidied, would recommend them + will use them again, hopefully for not a long time.</i></p>	<p>Date received: 3rd November 2025</p> <p>Total cost of work: Not provided</p> <p>Description of work: Replacing broken tiles and repairing gutting and cleaning all the guttering</p> <p>Comments: The men were polite, and quick and tidied, would recommend them and will use them again, hopefully for not a long time.</p>			
Customer Ratings (Out of 10)	9	9	10	10

<p>ONLINE FEEDBACK PROVIDED</p>	<p>Date received: 22nd October 2025</p> <p>Total cost of work: £1200</p> <p>Description of work: Couple of slate replaced front and back of house and new down pipe and guttering on front of house</p> <p>Comments: Excellent. They were very busy so you go in a list and they keep you updated with where you are on list. They came to me very quickly, highly recommended as they were very easy to deal with.</p>			
Customer Ratings (Out of 10)	10	10	10	10

<p>ONLINE FEEDBACK PROVIDED</p>	<p>Date received: 22nd October 2025</p> <p>Total cost of work: £1600</p> <p>Description of work: We needed our gutters replaced and some broken tiles, but also needed scaffolding so that did add to the cost.</p> <p>Comments: Taylor Roofs did a good job from start to finish. We have used them before and would use again. We did have a few small issues but they were sorted promptly without any problems.</p>			
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 17th October 2025</p> <p>Total cost of work: £2352</p> <p>Description of work: Roof cleaning of moss and a preventative solution applied.</p> <p>Comments: Roof cleaning of moss was completed over two days with a preventative solution applied at the end. Eight tiles were replaced after inspection when working to be cracked. From initial survey, to the work being completed was carried out in a satisfactory way. It was quite misty the weather and a bit slippy on the roof, but an extra team was called in to help with the work. Excellent service work area left clean and tidy, old moss removed from site. Advice on roof vents to be installed later.</p>				
	<table border="1"> <thead> <tr> <th data-bbox="834 619 1001 732">Value for money</th><th data-bbox="1001 619 1168 732">Quality of work</th><th data-bbox="1168 619 1334 732">Service</th><th data-bbox="1334 619 1501 732">Tidiness</th></tr> </thead> </table>	Value for money	Quality of work	Service	Tidiness
Value for money	Quality of work	Service	Tidiness		
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	<p>Date received: 15th October 2025</p> <p>Total cost of work: £2800</p> <p>Description of work: Roof repair and slates were fixed.</p> <p>Comments: ★★★★★ Review for Taylor Roofs Before getting in touch with Taylor Roofs, we had water pouring into our living room - not exactly the feature we were going for! From the initial quotation through to the guys turning up on the day, everything went smoothly. Communication with the office was spot on and the work itself was completed to a really high standard. We're delighted with the results and wouldn't hesitate to recommend Taylor Roofs to anyone needing roofing work done properly</p>				
	<table border="1"> <thead> <tr> <th data-bbox="834 1500 1001 1612">Value for money</th><th data-bbox="1001 1500 1168 1612">Quality of work</th><th data-bbox="1168 1500 1334 1612">Service</th><th data-bbox="1334 1500 1501 1612">Tidiness</th></tr> </thead> </table>	Value for money	Quality of work	Service	Tidiness
Value for money	Quality of work	Service	Tidiness		
Customer Ratings (Out of 10)	10	10	10	10	

ONLINE FEEDBACK PROVIDED	<p>Date received: 15th October 2025</p> <p>Total cost of work: £3000</p> <p>Description of work: Replace lead and tiles around chimney. Replace boards, felt and tiles to rear roof.</p> <p>Comments: Very professional, arrived when promised, completed on time. High quality work. Hard working and tidy. Office staff are very responsive. Will definitely use again.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	10	10	10

Total cost of the work £	<p>Date received: 7th October 2025</p> <p>Total cost of work: Not provided</p> <p>Description of work: Full tied roof replacement</p> <p>Comments: Excellent workers – a very professional job. Some nails have come through loft but that couldn't really be avoided – it has left some areas with broken plaster and paint.</p>			
Description of the work undertaken: <u>Full tiled roof replacement</u>	Value for money	Quality of work	Service	Tidiness
Your comments: <i>Excellent workers – a very professional job some nails have come through loft but that couldn't really be avoided – it has left some areas with broken plaster and paint</i>	10	10	10	9

ONLINE FEEDBACK PROVIDED	<p>Date received: 7th October 2025</p> <p>Total cost of work: £4630.26</p> <p>Description of work: Renew flat roof, fascia and guttering. Comes with a 10year certificate of guarantee for materials and workmanship.</p> <p>Comments: Blair and Craig came on time each morning, kept me informed, and worked hard to get the job completed before a storm was due. Very pleasant guys, tidied after themselves, and made the work go smoothly. I didn't get additional quotes due to paying £30 for their quote so not actually sure if this was a comparable price to what other companies would charge. However, I do have peace of mind now that the work is complete.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 3rd October 2025</p> <p>Total cost of work: £328</p> <p>Description of work: Replacement roof tiles</p> <p>Comments: We contacted Taylor Roofing as we wished to have the roof surveyed before the winter months and it was found we required some broken tiles replaced. Greg & Daryl provided a very professional, efficient and friendly service informing us of all works being carried out and also clear up thereafter. From Mark, surveyor, Greg and Daryl and contact with all their customer care team, we would highly recommend Taylor Roofing for any further works. Thank you for an excellent job.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 25th August 2025</p> <p>Total cost of work: £3500</p> <p>Description of work: Install dry ridge system and other roof repairs.</p> <p>Comments: Great to deal with, quick to respond and work done to a high standard.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	9

ONLINE FEEDBACK PROVIDED	<p>Date received: 1st August 2025</p> <p>Total cost of work: £4500</p> <p>Description of work: Roof repair, specialists lead flashing.</p> <p>Comments: First class job. Quality of workmanship was exceptional. Clean and tidy.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 28th July 2025</p> <p>Total cost of work: £12,434</p> <p>Description of work: Supply materials and fit a new roof.</p> <p>Comments: They turned up when they said they would and did an excellent job. The workmen were polite and pleasant, it was obvious when watching them work they knew exactly what they were doing. The gardens were left tidy. All in, very satisfied with the work. They are not the absolute cheapest, but you get what you pay for. the materials were all top quality, and no corners were cut when carrying out the work. I would thoroughly recommend this company.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 28th July 2025</p> <p>Total cost of work: £1014</p> <p>Description of work: Fix leaking roof by replacing broken tiles, also install 12 ventilation tiles to allow additional ventilation into the loft space.</p> <p>Comments: I was impressed by Taylor's service and wouldn't hesitate to use them again.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 14th July 2025</p> <p>Total cost of work: Not provided.</p> <p>Description of work: Dry verge and Ridge replacement.</p> <p>Comments: The guys were great. I could not ask for any better people to get the job done. Dry verge and Ridge replacement. I couldn't be any happier with the job.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 12th July 2025</p> <p>Total cost of work: £850</p> <p>Description of work: Replaced loose roof ridge tiles.</p> <p>Comments: From the initial phone call to completion of work we found no fault. A good company to deal with and all work satisfactory.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	<p>Date received: 26th June 2025</p> <p>Total cost of work: Not provided.</p> <p>Description of work: We got our gutters replaced and downpipes replaced front and back.</p> <p>Comments: Mark and Darryl were very nice and polite, got the job done, kept the place nice and tidy and were done in two days, cannot fault them, would highly recommend Taylor roofs if we need to get our roof replaced.</p>			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10