



COMMENTS AND RATINGS

West Lothian Trusted Trader Scheme

Taylor Roofs

NUMBER OF FEEDBACK FORMS RECEIVED: 485 (showing most recent 30)

AVERAGE SATISFACTION SCORE (OUT OF 10): 9.7

The following feedback forms have been completed by previous customers, rating their experience of dealing with Taylor Roofs.

ONLINE FEEDBACK PROVIDED	Date received: 6 th August 2026 Total cost of work: £276 Description of work: Guttering cleaning and roof repair. Comments: Annual roof survey undertaken, identified one or two problems. Estimate received on same day and work booked in for 3 weeks. Two roofers came and did the work to my great satisfaction. Roofers very courteous and extremely polite. Have used Taylor Roofs in the past and their service and work have been first class.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	10	10	10

Total cost of the work £13,559.83 Description of the work undertaken: ROOF REPLACEMENT Your comments: JOB VERY WELL DONE	Date received: 29 th June 2026 Total cost of work: £13,559.83 Description of work: Roof replacement. Comments: Job very well done.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 29th June 2026 Total cost of work: £8518.87 Description of work: Work involved replacing all the soffits, fascias, gutters and downpipes on my detached property, including the garage roof too. Price also included scaffolding that had to be erected. Comments: Fantastic job by Taylor Roofs. The whole process was seamless and professional from start to finish. The roofers who done the job (Darryl, Robbie, Craig and Adam) all worked extremely hard and the quality of the work is fantastic. This is the second time that I have used Taylor Roofs, and I would have no hesitation in using them again. I would definitely recommend them.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 20th June 2026 Total cost of work: £3096.86 Description of work: Rough casting our half of the chimney and new lead flashing, some minor tile repairs, cleaning the gutters. - They arrived and started working on the whole chimney not just our half and never asked the neighbour's for permission to use their garden for access. -Broke 6 ridge tiles which they then tried to repair with tiles that didn't fit and had no overlap between them. -They caused so much damage we asked them to stop before the tile repairs away from the chimney and ridge. -didn't tidy up Comments: I was really disappointed with Taylor roofs. We selected them despite the higher prices due to the good reviews but I wouldn't use them again. - 2-3 day job took 1 month. - Had to complain to the CEO twice to get a reasonable standard of work done. - Roofers would turn up for an hour and leave, no updates from the office to explain the delays. - They were screaming at each other on the roof and arguing all the time. - Final roofer sent was good, but so much hassle and very over priced.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	1	4	1	1

Total cost of the work £ <u>✓</u> Description of the work undertaken: <u>STRIP OLD FELT ROOFING OFF, AND REPLACE WITH NEW MATERIALS</u> Your comments: <u>EXCELLANT JOB DONE BY ALL THE GUYS WHO CAME TO OUT TO DO THE JOB. WELL SATISFIED WITH THE WORK THEY ALL CARRIED OUT. VERY HAPPY.</u>	Date received: 16th June 2026 Total cost of work: Not provided. Description of work: Strip old felt roofing off and replace with new material. Comments: Excellent job done by all the guys who came out to do the job. Well satisfied with the work they all carried out. Very happy.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

Total cost of the work £ <u>~ £615</u> Description of the work undertaken: <u>Repair several slipped slate tiles, cleaning out watergates, cleaning swan neck and moving the gutter so that window is able to open fully. Re-fit the roof strap at top ridge.</u> Your comments: <u>Very hard working team, very professional + friendly. Took pride + care of their work - we are very happy how everything was done. After completion job wasn't signed off as completed until a senior surveyor came to inspect the work done.</u>	Date received: 16th June 2026 Total cost of work: ~ £615 Description of work: Repair several slate tiles, cleaning out water gates, cleaning swan neck and moving the gutter so that window is able to open fully. Re-fit the roof strap at top ridge. Comments: Ver hard working team, very professional & friendly. Took pride & care of their work – we are very happy how everything was doe. After completion job wasn't signed off as completed until a senior surveyor came to inspect the work done.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 22nd May 2026 Total cost of work: £10508.60 Description of work: Full roof replacement with new gutters. Comments: All staff I have interacted with from booking the survey through to the work being completed have been incredible. The work was completed very quickly and done to a high standard. I would not hesitate to recommend Taylor roofs or have them back again if other work was required.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 22 nd May 2026 Total cost of work: £650 Description of work: This work was for my flat roof, a leak was sealed and roof was painted. Comments: The job was to paint my flat roof but a potential leak was identified so they came back a couple of days later to seal the felt and then the entire roof was to be painted. Sean has been here this morning and I'm more than happy the work has been completed satisfactorily.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	7	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 7 th May 2026 Total cost of work: £8000 Description of work: Complete re-roof of rear extension Comments: On the whole a very clean and professional job. The roofing team were always polite and helpful and obviously good at their job. When asked to remove scaffolding and skip promptly at the end of the work they obliged. Would I recommend them - Yes.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 18 th March 2026 Total cost of work: £138 Description of work: Securing of loose verge tiles on roof. Comments: Second time using Taylor Roofs and service was again good.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 10 th March 2026 Total cost of work: £300 Description of work: Survey roof and replace broken roof tiles. Comments: Very professional. Told me what they were going to do then done it. No fuss, no mess and very courteous.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	9	10	9

ONLINE FEEDBACK PROVIDED	Date received: 10 th March 2026 Total cost of work: £440 Description of work: Replacing missing ridge tile and replacing tiles broken by tile coming off. Comments: Professional and polite. Work was completed quickly and area left very tidy. Would definitely use them again to help with issues.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 4 th March 2026 Total cost of work: £12,434 Description of work: 1. Erect ladders for safe access. 2. Remove silicone at edges of window above bay window at front. 3. Install new silicone. 4. Remove cement joints on concrete sills at bay window. 5. Replace with new cement. 6. Tidy site. 7. Remove ladders from site. Comments: Easy enough to set up a roofing inspection - surveyor arrived at arranged time and phoned to give me about 30 minutes notice that he was on his way. Inspected roof area and discussed his findings with me - showing pictures. Estimate was provided in a couple of days, and although a little pricy, was happy to go ahead with it. Work was carried out as discussed and there was little or no trace of the visit, in terms of mess. No complaints at all.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	8	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 3 rd March 2026 Total cost of work: £650 Description of work: Retro fitting wire netting to solar panels. Comments: Taylor Roofing are competitively priced, friendly, professional and keep you updated of work progress. Payment is also made easy.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 23 rd February 2026 Total cost of work: £545.70 Description of work: Repair to leaking roof. Comments: Superb company to work with on all levels, highly recommend them.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 20 th February 2026 Total cost of work: £2051.36 Description of work: Replaced 26 year old gutters and downpipes back and front of property, including all fittings to masonry and flashings. Comments: All works carried out to a high standard and within a few days of accepting quotation. Extremely happy of the company's high standard of care throughout the whole process as we have come to expect over many years. Guys are very experienced helpful and friendly. We will continue our relationship as we welcome their experience in all roofing matters. Highly recommended if you are looking for a professional high standard job at your home.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 4th February 2026 Total cost of work: £1538 Description of work: Replace timber tile battens Install new felt Install new tile batten Reinstall tiles and repair flashing Smallish area above garage conversion. Comments: Quoted time for work was one day. They had finished within 2 hours. I complained: 1. Placement of ridge tile was incorrect 2. Time that I was quoted to the time it actually took Company came back 1. Improved the ridge tile (still sits proud compared to the others) 2. Repaired flashing 3. Cannot vouch for work under tiles They admitted the first job had been rushed. Zero confidence that the problem is fixed. They have repeatedly refused to give me a breakdown of costs.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	1	2	7	7

ONLINE FEEDBACK PROVIDED	Date received: 21st January 2026 Total cost of work: £750 Description of work: Fix leaking roof caused by tiles shifting after recent bad weather. Comments: The process from my initial call, through survey and quote, to fixing our roof leak was smooth and as fast as they could fit the work in. The Taylor Roofs team gave open communication and kept me well informed.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 21st January 2026 Total cost of work: £4500 Description of work: Strip and re felt garage flat roof. Comments: Trader kept me up to date until work started and although the weather was not very helpful all work was completed to my satisfaction and the site all cleared and left clean and tidy.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 19 th January 2026 Total cost of work: £142 Description of work: Repair to boiler flue on roof Comments: Can thoroughly recommend Taylor roofs. Everyone I dealt with was polite courteous and professional and did everything that they said they would. Why can't all companies be like this?			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 15 th January 2026 Total cost of work: £159 Description of work: Soil vent pipe leaking due to it not being routed & secured correctly. This was identified by Graeme, the surveyor, who took images of the problem and checked the vent & surrounding area on the roof. The pipe was routed and secured. Comments: From initial contact to completion of the work all staff I dealt with were friendly, professional and helpful. The surveyor and workmen came at the advised time and left the house as they found it. The cost of the repair was within the price range I expected. I would not hesitate to recommend / use Taylor Roofs in the future.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 8 th January 2026 Total cost of work: £404 Description of work: Replaced roof tiles and roof lead to fix roof leaks. Comments: Excellent company, brilliant customer service and fantastic quality of work.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 12 th December 2025 Total cost of work: £540 Description of work: Gutter and waterway clean on a large roof. Comments: Taylor Roofs are excellent - always send quotes, invoices and receipts. Give plenty of advice and flexibility for when work is completed. The workmen are always prompt and courteous, do the work thoroughly and leave the place clean and tidy. I would recommend them.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	7	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 9 th December 2025 Total cost of work: £760 Description of work: Roof repair Comments: Excellent job, with no hassle whatsoever. Thank you very much, Taylor Roofs.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 26 th November 2025 Total cost of work: £493 Description of work: Replacing roof tiles and mending the roof line. Comments: Excellent service from start to finish, what and Robbie who did the on-site work very professional and pleasant.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 17th November 2025 Total cost of work: £8400 Description of work: Dry hip and ridge replacement. Comments: Very satisfied with all aspects of the job. Initial surveyor was very professional and knowledgeable and we were kept informed by the friendly office staff as to when the work would commence. Reece was with us for all four days and made sure that we were kept up to date on progress. He and all the other roofers were courteous throughout. All areas were left very clean and tidy on completion. We would definitely recommend this company.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	10	10	10

ONLINE FEEDBACK PROVIDED	Date received: 13th November 2025 Total cost of work: £5000 Description of work: New garage flat roof. Comments: We are really highly satisfied with the work completed on my mother's garage roof. The guys were great and highly skilled. They kept my Mum up to date with all the work and showed her photos of the progress. The office staff kept us informed and communicated very well with us. We highly recommend Taylor Roofs for a highly quality job. They even tidied up after themselves! I was sent out to sweep up but it had already been done. That doesn't happen very often!!			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	10	10	10

Total cost of the work £ <u>1991.50</u> Description of the work undertaken: <u>REMOVE BEDDED WET RIDGE TILE SYSTEM AND</u> <u>REPLACE WITH DRY RIDGE SYSTEM INCLUDING NEW</u> <u>TILE VENT FOR SHOWER EXTRACTOR FAN EXHAUST.</u> Your comments: <u>WORK BUDGETED FOR ONE DAY BUT EXTENDED TO</u> <u>6 DAY DURATION DUE TO HIGH WIND.</u>	Date received: 12th November 2025 Total cost of work: £1991.50 Description of work: Remove bedded wet ridge tile system and replace with dry ridge system including new tile vent for shower extractor fan exhaust. Comments: Work budgeted for one day but extended to 6 day duration due to high winds.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	7	9	9	9

Total cost of the work £ <u>£3,915.54</u> Description of the work undertaken: <u>Repair of a large roof join between two attached</u> <u>cottages</u> Your comments: <u>Job completed without any fuss.</u>	Date received: 11th November 2025 Total cost of work: £3915.54 Description of work: Repair of a large roof join between two attached cottages. Comments: Job completed without any fuss.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	9	N/A	10	10

Total cost of the work £ <u>765</u> Description of the work undertaken: <u>Removal of birds nests from under solar panels.</u> <u>Fit barrier around solar panels to avoid future problems</u> Your comments: <u>A few problems with correct materials but eventually</u> <u>sorted out.</u>	Date received: 3rd November 2025 Total cost of work: £765 Description of work: Removal of birds' nests from under solar panels. Fit barrier around solar panels to avoid future problems. Comments: A few problems with correct materials but eventually sorted out.			
	Value for money	Quality of work	Service	Tidiness
Customer Ratings (Out of 10)	10	N/A	10	10